

10/08/10 5:15:56 PM

35

33

30

31

50

1A21

37

25

23

Fig 1

Spec Act

22141 80 SHEETS  
22142 100 SHEETS  
22144 200 SHEETS

AMPRO

FOOT 60" ST 1556160




FIG. 2

PRIOR ART

Figure 3





Fig 4



PRIOR  
ART




Figure 5

1000160-51456660





Figure 6






Figure 6b




Figure 7

1001000-51435610




Figure 8

0005615-09-001






Figure 9




1120  
Figure 10

Bode Response with Torque Disturbance at HDA Actuator

TO 8860 ST 56160



TR08T60-5T-155660



1320

Figure 12

Response Due to Torque Disturbance at HDA Actuator  
with Soft Material between HDA and Positioner




Figure 13

091805-15:56560

TO8T60-STress600




Figure 14

TO 8760-575560




Figure 15




Figure 16